SnowDocic Buyers					TECHNICAL SERVICE BULLETIN					
NUMBER	16TSB-79			TYPE	SERVICE ALE				LERT	
ROUTING	INSTALL	Х	SERVICE	Х	SALES		PURCH			
TITLE	2017 G2 CHAIN LIFT/STACKING STOP									
REV	Α			ISSUED	11	/2/2	018	REVISED	-	
AFFECTS	ALL 2017 G2 PLOWS, 1601X002/1601X022, 16111408 CHAIN LIFT									
INFORMATION	ALL 2017 G2 PLOWS, 1601X002/1601X022, 16111408 CHAIN LIFT The G2 chain lift design has been changed to eliminate the need for separate chain clips or the possibility of improper chain assembly that can lead to damage to the chain lift. This is a drop in replacement and any 2017 plow can be updated as necessary. A stacking stop (16111164) has also been developed that should be added to the plow as well. These parts are available together as a kit under PN 3039787.									
CORRECTION	be replaced with	i 3039 lude ii	787. This	kit contain	s 1611	1408A	and 161	11146. B	for warranty - it will oth kits are easily g customer service	